

CERTIFICATE OF CONFORMITY

CERTIFICATE No.: HMT21.4164X



1 Equipment intended for use in potentially explosive atmospheres
Directive 2014/34/EU

2 Certificate N°: HMT21.4164X Issue 0

3 Manufacturer: Heinrichs Messtechnik GmbH

4 Address: Robert-Perthel-Str. 9

50739 Cologne Germany

5 Products: **V31** Glass-Tube Variable Area Flow-Meter

Heinrichs Messtechnik GmbH Tel.: +49 221 49 708-0 www.heinrichs.eu info@heinrichs.eu

- In accordance to Annex VIII of the Directive 2014/34/EU, *Module A: Internal Production Control*, Heinrichs Messtechnik GmbH ensures in sole responsibility that the products concerned in this certificate of conformity satisfy the requirements of this Directive. The internal production assessment procedure performed for the above mentioned products fulfils the obligations laid down in points 2, 3 and 4 of Annex VIII and are compliant to the Essential Health and Safety Requirements relating to the design and construction of product intended for use in potentially explosive atmospheres.
- 7 The technical documentation has been submitted for 5 year depository to the EU notified body; DEKRA Testing and Certification GmbH (Notified Body number 0158)
- The 'X' suffix after the certificate number indicates that the equipment is subject to conditions of safe use.

 These are specified in section 14
- 9 Compliance with the Essential Health and Safety Requirements has been demonstrated through compliance with the following documents:

EN 1127-1:2019

EN 80079-36:2016

10 The equipment marking shall include the following:

(ξx)

II 2G Ex h IIC T6 Gb

II 2d Ex h IIIC T85°C Db

Heinrichs Messtechnik GmbH Cologne 17.02.2021

Signed:

Joseph Burke

(Explosion Protection Representative)

5.13k



11 Description

11.1 Product description

The V31 is suitable for the flow-measurement of fluids or gases in pipe systems.

The momentary flow volume or mass is indicated pro time unit on a scale printed on to the glass measuring tube. Alternatively, the measuring tube is available with a percent or 2 mm scale.

The devices may be fitted with electrical limit switches. The switches must be certified or assessed for the prevailing installation environment.

11.2 Model Code:

```
V31*- AAAAAA - BBCCD - E F G H I - I K LL M N O P O R XXX
     Process Connections
         Float Properties
             Measuring Range
         D:
                Medium
             E:
                    Glass Tube Sealing Gasket
                F:
                       Float Stopper
                    G:
                           Union Nut Material
                              Shatter protection
                                 Electrical equipment (Contacts)
                                                                                                 Restrictions:
                                 0 = None
                                                                                                 <u>T<sub>amb</sub></u> = -20 ... 80 °C
                                 1 = 1x GSGA (NC)
                                                                                                 <u>T<sub>amb</sub></u> = -20 ... 80 °C
                                                                                                 T_{amb} = -20 ... 80 \, ^{\circ}C
                                 2 = 1x GSGB (NO)
                                                                                                 <u>T<sub>amb</sub></u> = -20 ... 80 °C
                                 3 = 1x GSGW (SPDT)
                                 4 = 2x GSGA (NC)
                                                                                                 T_{amb} = -20 ... 80 \, ^{\circ}C
                                 5 = 2x GSGB (NO)
                                                                                                 T<sub>amb</sub> = -20 ... 80 °C
                                     Scale
                                 K:
                                        Certificates
                                            Calibration
                                                Cleaning acc. factory standards
                                                  Pressure / Leakage test
                                                     Approvals
                                                         Marking Tags
                                                            Supp. Equipment
                                                               Company Design
                                                                  Up to 6 further non-Ex
                                                                  relevant positions
```



11.3 Certificate and evaluation report history

Issue N°.	Date	Associated Reports	Notes	
	07.10.2010	HM-V31-ATEX-10-	Original document submission, according to	
		02-X	DIN EN 13463-1:2009, for a retention period of	
			10 years	
0	19.10.2020		Extension of retention period for a further 5 years	

11.4 Temperatures

The equipment's temperature class, surface temperature and equipment protection levels are dependent upon the ambient and process temperatures as follows:

Ambient Temperature	Process	Temperature	Temperature
	Temperature	class Gas	Class Dust
-40 80 °C	-40 80 °C	T6	85 °C

With the addition of electrical equipment, a further restriction of the maximum ambient and process temperature may be required. Refer to the EU Type Approval of the relevant electrical component and the meter operating manual for further information for the determination of the prevailing temperature class.

12 Specific Conditions of Use

- 12.1 By the measurement of non-conductive medium, the earthing of the equipment is essential to ensure a build-up of static electricity within the meter is suppressed.
- 12.2 When installed and operated in potentially explosive dust environments, the device must be cleaned regularly in order to avoid deposits exceeding 5 mm. Clean with a damp cloth.
- 12.3 The polycarbonate glass tube protection hood exceeds the maximum permissible surface area specified in DIN EN ISO 80079-36:2016 / 6.7.5. When installed in potentially explosive atmospheres, it is to be ensured that electrostatic charge in dangerous quantities cannot occur.

Do not rub the hood with a dry cloth.